

Daily Supply Chain Movement Report

Date: 06 December 2023, 14:00

Entire Port

Port	Vessels		Resources
Port of Cape Town	Vessels at anchorage: 7	Tanker: 5, Fishing: 2.	3 tugs, 1 launch and 1 pilot boat
	Vessels at berth: 9	CTCT: 2, CTMPT: 2, FPT: 1, Other terminals: 4.	

Container Terminals

Port Terminal	Marine operations	Waterside operations ¹	Landside operations ¹	Stack occupancy
Cape Town Container Terminal	Vessels at anchorage: 0 Vessels at berth: 2 (Santa Teresa, Maersk Cadiz)	Actual: no volumes Average: 1 901 TEUs	Actual: no trucks Rail: no containers	General: 27% Reefer: 24% Empties: 56%

Bulk operations

Port Terminal	Marine operations	Waterside operations ²	Landside operations ⁴	Stack occupancy
Cape Town				
MPT	Vessels at anchorage: 0 Vessels at berth: 2	Bulk: 1 662 tons	Actual: 97 trucks	General: 36% Reefers: 34% Empties: 55%
FPT (Private terminal) 8	Vessels at berth: 1	Not reported	Not reported	Not reported
Saldanha Bay				
IOT	Vessels at anchorage: 0 Vessels at berth: 1	The vessel at anchorage has been waiting outside for 7-8 days, while vessels at berth have been at port for 1-3 days.		
MPT	Vessels at anchorage: 2 Vessels at berth: 3			

¹ Average refers to the average performance for 2022, using the information available.

² Average refers to the average performance for 2022, using the information available.

Other Updates:

Operational comments and general observations
<p>Weather and other delays:</p> <ul style="list-style-type: none">CTCT was windbound for the entire 24 hours yesterday, which significantly impacted operations at the port. The two vessels on berth at CT MPT were delayed for approximately 18 hours due to strong winds. As a result, only about 54 TEUs were handled.
<p>Load-shedding:</p> <ul style="list-style-type: none">No load-shedding was reported at any of our national ports and terminals over the past 24-hour period.
<p>Equipment Availability:</p> <ul style="list-style-type: none">Due to the adverse weather conditions in Cape Town, the replacement of the energy chain on crane LC4 could not be executed. OEM, Liebherr, is on site today to complete the replacement.
<p>Staging Areas Update:</p> <ul style="list-style-type: none">Nothing to report for the past 24-hours.
<p>Bottlenecks: No current update</p>
<p>Rail Update: No current update</p>